

Tel.: +82-31-500-0133

Fax.: +82-31-500-0159



SAR Measurement Setup Photos UM100





Test Sample Photo – UM100



<close>



<open>







<front>



<rear>







<left side>



<right side>







<top>



Fax.: +82-2-860-1468



HP Compaq nc2400



<close>



<open>



Fax.: +82-2-860-1468



Direct connection SAR setup photos





<Horizontal down>







<EUT Top facing phantom>



Fax.: +82-2-860-1468



USB cable connection SAR setup photos



<Horizontal up>



<Horizontal down>







<Vertical up>



<Vertical down>







<Top>



<USB Cable>