




1. Photographs of Conducted Emissions Test Configuration



Report No. : FR851627AC

Front view



Side view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 1 of 6
Report Version : Rev. 01







Report No. : FR851627AC

Under Table View

SPORTON INTERNATIONAL INC. Page No. : 2 of 6
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973



Report No.: FR851627AC

2. Photographs of Radiated Emissions Test Configuration – Mode 1 For radiated emissions below 1G

PIFA Antenna



Front view



Rear view


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 3 of 6 Report Version : Rev. 01




Report No.: FR851627AC

For radiated emissions above 1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973



Report No.: FR851627AC

3. Photographs of Radiated Emissions Test Configuration – Mode 2 For radiated emissions below 1G Dipole Antenna



Front view



Rear view


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 5 of 6 Report Version : Rev. 01




Report No.: FR851627AC

For radiated emissions above 1GHz



Front view



Rear view

——THE END——

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 6 of 6 Report Version : Rev. 01