


1. Photographs of Conducted Emissions Test Configuration – Mode 1



Front view




Side view

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 1 of 8
EP Report Version : Rev. 01
Issued Date : Jul. 19, 2018





Under Table View

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 2 of 8
EP Report Version : Rev. 01
Issued Date : Jul. 19, 2018



2. Photographs of Conducted Emissions Test Configuration – Mode 2



Front view




Side view

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 3 of 8
EP Report Version : Rev. 01
Issued Date : Jul. 19, 2018






Under Table View

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 4 of 8
EP Report Version : Rev. 01
Issued Date : Jul. 19, 2018



3. Photographs of Radiated Emissions Test Configuration – Mode 1 For radiated emissions below 1G



Front view




Rear view

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 5 of 8 EP Report Version : Rev. 01 Issued Date : Jul. 19, 2018



For radiated emissions above 1GHz



Front view




Rear view

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 6 of 8
EP Report Version : Rev. 01
Issued Date : Jul. 19, 2018



4. Photographs of Radiated Emissions Test Configuration – Mode 2 For radiated emissions below 1G



Front view




Rear view

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 7 of 8 EP Report Version : Rev. 01 Issued Date : Jul. 19, 2018



For radiated emissions above 1GHz



Front view



Rear view

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 8 of 8
EP Report Version : Rev. 01
Issued Date : Jul. 19, 2018