
Report No.: 60608301 Page \_\_\_25 \_\_of \_\_\_50


## **Internal Photo**







Report No.: 60608301


Page \_\_\_\_\_ 26 \_\_\_ of \_\_\_\_ 50







Report No.: 60608301 Page <u>27</u> of <u>50</u>






Report No.: 60608301 Page 28 of 50






Report No.: 60608301


Page <u>29</u> of <u>50</u>







Report No.: 60608301 Page 30 of 50







Report No.: 60608301 Page 31 of 50







Report No.: 60608301 Page 32 of 50







Report No.: 60608301 Page 33 of 50






Report No.: 60608301 Page 34 of 50






Report No.: 60608301 Page \_\_\_35\_\_of \_\_50\_\_






Report No.: 60608301 Page 36 of 50






Report No.: 60608301 Page 37 of 50





Report No.: 60608301 Page 38 of 50





Report No.: 60608301 Page 39 of 50






Report No.: 60608301 Page 40 of 50





Report No.: 60608301
Page 41 of 50




Report No.: 60608301 Page \_\_\_\_ 42 \_\_\_ of \_\_\_\_ 50

## **Power Adapter**






Report No.: 60608301 Page <u>43</u> of <u>50</u>





Report No.: 60608301 Page 44 of 50





Report No.: 60608301 Page \_\_\_45 \_\_of \_\_\_50







Report No.: 60608301 Page <u>46</u> of <u>50</u>




Report No.: 60608301 Page <u>47</u> of <u>50</u>






Report No.: 60608301 Page 48 of 50





Report No.: 60608301 Page <u>49</u> of <u>50</u>





Report No.: 60608301 Page <u>50</u> of <u>50</u>

