

## **Class II Change Letter**

Date: August 14, 2006

## To Whom It May Concern:

Please be advised that Taiwan Semiconductor Co. Ltd. changed the schematics as following for the approved FCC ID:UES2006001 due to some CE testing items are failed.

	Old	New
SPI 4 pins	Linked to connector J2	Can not link to connector
LED	Linked to connector J1	Can not link to connector
Reset to default	Linked to connector J1	Can not link to connector
Wiring	On Top layer	On Bottom layer
Ground	On Bottom layer	On both Top layer and Bottom layer

Thank you for your attention to this matter.

(Signature)

Sincerely,

Lion Ho

Supervisor

Thermal Printer Division

Lion Ho