
Appendix C. Set up Photograph

Conducted Emission

Mode 1~2



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UFOBC0164AAA390 Page Number : C1 of C6
Report Issued Date : Jul, 17, 2007
Report Version : Rev. 01

Report No. : FR762206-B



SIDE VIEW

Mode 3~5




FRONT VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UFOBC0164AAA390 Page Number : C2 of C6
Report Issued Date : Jul, 17, 2007
Report Version : Rev. 01





REAR VIEW



SIDE VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UFOBC0164AAA390 Page Number : C3 of C6
Report Issued Date : Jul, 17, 2007
Report Version : Rev. 01



Mode 4



FRONT VIEW




REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UFOBC0164AAA390 Page Number : C4 of C6
Report Issued Date : Jul, 17, 2007
Report Version : Rev. 01





SIDE VIEW

SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UFOBC0164AAA390 Page Number : C5 of C6
Report Issued Date : Jul, 17, 2007
Report Version : Rev. 01



Radiation Emission



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UFOBC0164AAA390 Page Number : C6 of C6
Report Issued Date : Jul, 17, 2007
Report Version : Rev. 01