
Appendix C. Set up Photograph

Spurious Radiation Model 1



FRONT VIEW

REAR VIEW


SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UFOBC0164AAA390 Page No. : C1 of C3
Report Issued Date : Jul. 23, 2007
Report Version : Rev.01

Report No.: FG762206-A

Report No.: FG762206-A

Spurious Radiation Model 2



FRONT VIEW

REAR VIEW


SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UFOBC0164AAA390

: C2 of C3 Page No. Report Issued Date : Jul. 23, 2007

Report Version : Rev.01 Report No.: FG762206-A

Spurious Radiation



FRONT VIEW





REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UFOBC0164AAA390

: C3 of C3 Page No. : Jul. 23, 2007 Report Issued Date

Report Version : Rev.01