

Mode 4 Horizontal Polarization





Site Condition EUT Power Model Memo	03CH06-HY		Mode+Adap	tor			
	Freq	Level	Over Limit	Limit Line	Read Level	Factor	Remark
	MHz	dB™	dВ	dBm	dBm	dВ	
1 @ 2 @ 3 @	754. 30 799. 80 1000. 00		-50.66	-13.00	0.50	-1.69	2000000

#### SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : UG8C-2007-19

Page No. : 91 of 110
Report Issued Date : Mar. 20, 2007

Report No.: FG721401

Report No.: FG721401




-42.80 -0.81 Peak -45.07 -1.11 Peak

l @ 2 @ Remark:

1. #1: Downlink Signal

1928.00 -43.61 1964.00 -46.18

2. #2: Downlink Signal




SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255


FCC ID : UG8C-2007-19

Page No. : 92 of 110
Report Issued Date : Mar. 20, 2007
Report Version : Rev. 02

Report No.: FG721401



TIGGE: (DISCRETE)
: 03CH06-HY
: HF-SPURIOUS HORIZONTAL
: Repeater
: 120Vac/60Hz
: FG 721401
: PCS 1930.2 MHz Downlink Mode+Adaptor





TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : UG8C-2007-19

: 93 of 110 Report Issued Date : Mar. 20, 2007

Vertical Polarization





#### SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : UG8C-2007-19

Page No. : 94 of 110
Report Issued Date : Mar. 20, 2007
Report Version : Rev. 02


Report No.: FG721401

#### FCC TEST REPORT Report No.: FG721401



# 1 @ 2 @ Remark:

- 1. #1: Downlink Signal
- 2. #2: Downlink Signal





SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

: UG8C-2007-19 FCC ID

: 95 of 110 Report Issued Date : Mar. 20, 2007





Remark: There is no more obvious spurious emission except the listings above.


SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : UG8C-2007-19

Page No. : 96 of 110
Report Issued Date : Mar. 20, 2007
Report Version : Rev. 02

Mode 5 Horizontal Polarization





#### SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : UG8C-2007-19

Page No. : 97 of 110
Report Issued Date : Mar. 20, 2007
Report Version : Rev. 02

Report No.: FG721401

Report No.: FG721401




Frace: (Discrete;
: 03CH08-HY
: HF-SPURIOUS HORIZONTAL
: Repeater
: 120Vac/60Hz
: FG 721401
: PCS 1960 MHz Downlink Mode+Adaptor

Over Limit
: mit Line

	Level	0ver	Limit	Read Level	Factor	Remark
MHz	<b>d</b> Bm	<u>dB</u>	<b>dB</b> m	<b>dB</b> m	<u>dB</u>	
	-47. 72 -46. 98			-45.87	-0.94 -1.11	Peak

# 1 @ 2 @ 3 @ Remark:

- 1. #1: Downlink Signal
- 2. #2: Downlink Signal
- 3. #3: Downlink Signal




SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

: UG8C-2007-19 FCC ID


: 98 of 110 Report Issued Date : Mar. 20, 2007 Report Version : Rev. 02

Report No.: FG721401



Site Condition EUT

Trace: (Discrete)
: 03CH06-HY
: HR-SPURIOUS HORIZONTAL
: Repeater
: 120Yag-76Hz
: FG 721401
: PCS 1960 MHz Downlink Mode+Adaptor




TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

: UG8C-2007-19 FCC ID


: 99 of 110 Report Issued Date : Mar. 20, 2007

#### Vertical Polarization



Site Condition EUT Power Model Memo

Read Freq Level Limit Line Level Factor Remark MHzdBmdBdBmdBm dВ 43. 23 -44. 56 -31. 56 -13. 00 -31. 66 -12. 90 Peak 56. 73 -43. 76 -30. 76 -13. 00 -29. 92 -13. 84 Peak 71. 58 -43. 37 -30. 37 -13. 00 -31. 63 -11. 74 Peak



Site Condition EUT Power Model Memo

1 @ 2 @ 3 @

MHz dBm ₫B dBm dBm dВ 1.43 Peak 2.35 Peak 2.63 Peak


#### SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : UG8C-2007-19

: 100 of 110 Report Issued Date : Mar. 20, 2007

Report No.: FG721401



Site Condition EUT Power Model Memo

1 @ 2 @ 3 @


Trace: (Discrete)

03CH06-HV
HF-SPURTOUS VERTICAL
Repeater
120Vac/50Hz
FC 721401
PCS 1960 MHz Downlink Mode+Adaptor
Over Limit

Freq	Level		Limit Line	Read Level	Factor	Remark
MHz	<b>dB</b> m	<u>dB</u>	dBπ	dBm	dB	
	-48. 42 -47. 36 -51. 11				-0.50 -0.60 -0.69	Peak

#### Remark:

1. #1: Downlink Signal 2. #2: Downlink Signal 3. #3: Downlink Signal



Trace: (Discrete)
: 03CH06-HY
: HR-SPURIOUS VERTICAL
: Repeater
: 120Vac/60Hz
: FG 721401
: PCS 1960 MHz Downlink Mode+Adaptor

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

: UG8C-2007-19 FCC ID


: 101 of 110 Report Issued Date : Mar. 20, 2007


: 102 of 110

: Rev. 02

Report Issued Date : Mar. 20, 2007

Report Version






Remark: There is no more obvious spurious emission except the listings above.


SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : UG8C-2007-19

Mode 6 Horizontal Polarization





#### SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : UG8C-2007-19

Page No. : 103 of 110
Report Issued Date : Mar. 20, 2007

Report No.: FG721401

Report No.: FG721401 File: D:Project\2007Q1\可危隆\721401\H-Channel\H-Channel-Down Link\Part24E.EMI (20 Date: 2007-03-14 FCC PART22/24




1974.00 -46.77 1988.00 -43.60 1 @ 2 @

-45.66 -1.11 Peak -42.33 -1.28 Peak

#### Remark:

- 1. #1: Downlink Signal
- 2. #2: Downlink Signal



Trace: (Discrete)
: 03CH06-HY
: HF-SPURIOUS HORIZONTAL
: Repeater
: 120Vac/60Hz
: FG 721401
: PCS 1989.8 MHz Downlink Mode+Adaptor


SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255


: UG8C-2007-19 FCC ID

: 104 of 110 Report Issued Date : Mar. 20, 2007

Report No.: FG721401



TIACE: (DISCRETE)
: 03CH06-HY
: HF-SPURIOUS HORIZONTAL
: Repeater
: 120Vac/60Hz
: FG 721401
: PCS 1989.8 MHz Downlink Mode+Adaptor




TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : UG8C-2007-19


: 105 of 110 Report Issued Date : Mar. 20, 2007

#### Vertical Polarization



Site Condition EUT Power Model Memo

dВ dBm MHzdBmdBmdВ 42.69 -44.63 -31.63 -13.00 -32.00 -12.63 Peak 56.19 -43.93 -30.93 -13.00 -29.95 -13.98 Peak 71.58 -43.78 -30.78 -13.00 -32.04 -11.74 Peak



Site Condition EUT Power Model Memo

1 @ 2 @ 3 @

Freq			Limit		Factor	Remark
MHz	dBm	dB	dB™	dBm	dB	
	-61.31	-48.37 -48.31 -48.18	-13.00	-63.68	2.37	Peak Peak Peak


#### SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

: UG8C-2007-19 FCC ID

: 106 of 110 Report Issued Date : Mar. 20, 2007

Report No.: FG721401




Freq	Level	Limit	Line	Level	Factor	Remark
MHz	<b>dB</b> m	<u>dB</u>	<b>dB</b> m	dBm	dB	
1944.00 1974.00 1988.00	-49.44			-48.85	-0.50 -0.60 -0.69	Peak

#### Remark:

1 @ 2 @ 3 @

1. #1: Downlink Signal 2. #2: Downlink Signal 3. #3: Downlink Signal




DISCHEE-NY
HR-SPURIOUS VERTICAL
Repeater
120Yac/60Hz
FG 721401
PCS 1989.8 MHz Downlink Mode+Adaptor

SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

: UG8C-2007-19 FCC ID

: 107 of 110 Report Issued Date : Mar. 20, 2007



Site Condition EUT Power Model Memo Trace: (Discrete)
: 03CH06-HY
: HH-SPUBRIOUS VERTICAL
: Repeater
: 120Vac/60Hz
: FG 721401
: PCS 1989.8 MHz Downlink Mode+Adaptor



Remark: There is no more obvious spurious emission except the listings above.

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : UG8C-2007-19

Page No. : 108 of 110
Report Issued Date : Mar. 20, 2007

# **5. List of Measurement Equipments**

Instrument	Manufacturer	Model No.	Serial No.	Characteristics	Calibration Date	Due Date	Remark
Spectrum analyzer	Agilent	E4408B	MY44211030	9KHz-26.5GHz	Jul. 25, 2006	Jul. 24, 2007	Radiation (03CH06-HY)
Receiver	R&S	ESCS30	100356	9KHz-2.75GHz	Jun. 28, 2006	Jun. 27, 2007	Radiation (03CH06-HY)
Controller	СТ	SC100	N/A	N/A	N/A	N/A	Radiation (03CH06-HY)
Bilog Antenna	SCHAFFNER	CBL6112B	2885	30MHz -2GHz	Nov. 21, 2006	Nov. 21, 2008	Radiation (03CH06-HY)
Horn Antenna	Com-Power	AH118	071025	1G-18G	Mar. 29, 2006	Mar. 29, 2007	Radiation (03CH06-HY)
SHF-EHF Horn	SCHWARZBECK	BBHA 9170	9170-249	14G - 40G	Jul. 21, 2006	Jul. 20, 2007	Radiation (03CH06-HY)
Amplifier	MITEQ	AMF-6F	997165	26G - 40G	Jul. 21, 2006	Jul. 20, 2007	Radiation (03CH06-HY)
Turn Table	HD	DS 420	420/650/00	0 ~ 360 degree	N/A	N/A	Radiation (03CH06-HY)
Antenna Mast	HD	MA 240	240/560/00	1 m - 4 m	N/A	N/A	Radiation (03CH06-HY)
Power Meter	Agilent	E4416A	GB41292344	N/A	Feb. 08, 2007	Feb. 08, 2008	Radiation (03CH06-HY)
Power Sensor	Agilent	E9327A	US40441548	N/A	Feb. 08, 2007	Feb. 08, 2008	Radiation (03CH06-HY)

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : UG8C-2007-19

Page No. : 109 of 110
Report Issued Date : Mar. 20, 2007
Report Version : Rev. 02

Report No.: FG721401

# 6. Uncertainty Evaluation

# Uncertainty of Radiated Emission Measurement (30MHz ~ 1000MHz)

Contribution	Uncerta			
	٩D	Probability	$u(x_i)$	
	dB	Distribution		
Receiver reading	0.41	Normal(k=2)	0.21	
Antenna factor calibration	0.83	Normal(k=2)	0.42	
Cable loss calibration	0.25	Normal(k=2)	0.13	
Pre Amplifier Gain calibration	0.27	Normal(k=2)	0.14	
RCV/SPA specification	2.50	Rectangular	0.72	
Antenna Factor Interpolation for Frequency	1.00	Rectangular	0.29	
Site imperfection	1.43	Rectangular	0.83	
Mismatch	+0.39/-0.41	U-shaped	0.28	
combined standard uncertainty Uc(y)		1.27		
Measuring uncertainty for a level of confidence of 95% U=2Uc(y)		2.54		

# **Uncertainty of Radiated Emission Measurement** (1GHz ~ 40GHz)

Contribution	Uncertainty of $x_i$			Ci	$Ci*u(x_i)$
	dB	Probability Distribution	$u(x_i)$		
Receiver reading	±0.10	Normal(k=1)	0.10	1	0.10
Antenna factor calibration	±1.70	Normal(k=2)	0.85	1	0.85
Cable loss calibration	±0.50	Normal(k=2)	0.25	1	0.25
Receiver Correction	±2.00	Rectangular	1.15	1	1.15
Antenna Factor Directional	±1.50	Rectangular	0.87	1	0.87
Site imperfection	±2.80	Triangular	1.14	1	1.14
Mismatch Receiver VSWR $\Gamma$ 1= 0.197 Antenna VSWR $\Gamma$ 2= 0.194 Uncertainty=20log(1- $\Gamma$ 1* $\Gamma$ 2* $\Gamma$ 3)	+0.34/-0.35	U-shaped	0.244	1	0.244
Combined standard uncertainty Uc(y)			2.36		
Measuring uncertainty for a level of confidence of 95% U=2Ue(y)			4.72		

# **END OF TEST REPORT**

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : UG8C-2007-19

Page No. : 110 of 110
Report Issued Date : Mar. 20, 2007

Report No.: FG721401