
http://mail.google.com/mail/?view=page&name=gp&ver=sh3fib53pgpk Netalog, Inc. d/b/a Digital Lifestyle Outfitters, FCC ID: UIX0702A, Assessment NO.: AN07T6738, Notice#1 Inbox from "tim.dwyer@ccsemc.com" <tim.dwyer@ccsemc.com> hide details Apr 22 (2 days ago) - Reply to Thu.Chan@ccsemc.com cc tim.dwyer@ccsemc.com date Apr 22, 2007 9:00 AM subject Netalog, Inc. d/b/a Digital Lifestyle Outfitters, FCC ID: UIX0702A, Assessment NO.: AN07T6738, Notice#1 Hello Thu, The review is complete. There are few administrative issues shown below. Note that I will also send the identical notice for related project AN07T6739. AN07T6738 Netalog UIX0702A Q1. The radio device on the schematic is identified as 433.92 MHz, but the application is for 915.92 MHz operation. Please verify that correct schematic has been submitted. Q2. 2.925 requires specifically that the FCCID to be preceded by "FCCID:" The label as submitted has "FCC:" Please provide corrected label artwork or drawing. Q3. Since the product connects to a PC, in addition to statement from 15.19, the following user manual statements from 15.105 and 15.21 are required. Please provide a revised user manual. NOTE: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures: -- Reorient or relocate the receiving antenna. -- Increase the separation between the equipment and receiver. Connect the equipment into an outlet on a circuit different from that to which the receiver is connected. -- Consult the dealer or an experienced radio/TV technician for help. Changes or modifications not expressly approved by <the party responsible for compliance> could void the user's authority to operate the equipment. The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender. Reply «Reply to all —Forward Invite tim.dwyer@ccsemc.com to Gmail from Thu Chan <thu.chan@ccsemc.com> hide details Apr 23 (1 day ago) - Reply to "Timothy M. Dwyer" <tim.dwyer@ccsemc.com> cc September Radecki < september.radecki@ccsemc.com>, Thu Chan <thu.chan@ccsemc.com> date Apr 23, 2007 1:33 AM subject RE: Netalog, Inc. d/b/a Digital Lifestyle Outfitters, FCC ID: UIX0702A, Assessment NO.: AN07T6738, Notice#1 We will address the questions ASAP.



Reply Reply to all Forward Invite Thu to Gmail

hide details 8:05 pm (10 minutes ago)



- to "Timothy M. Dwyer" <tim.dwyer@ccsemc.com>
- cc Thu Chan <thu.chan@ccsemc.com>,
- Erica Yueh <erica.yueh@ccsemc.com>

date Apr 24, 2007 8:05 PM

subject RE: Netalog, Inc. d/b/a Digital Lifestyle Outfitters, FCC ID: UIX0702A, Assessment NO.: AN07T6738, Notice#1

hi Tim.

Attached are the replies to your questions on the above application:

AN07T6738 Netalog UIX0702A

Q1. The radio device on the schematic is identified as 433.92 MHz, but the application is for 915.92 MHz operation. Please verify that correct schematic has been submitted.

<CCS Answer:> Please see attached schematic.

Q2. 2.925 requires specifically that the FCCID to be preceded by "FCCID:" The label as submitted has "FCC:" Please provide corrected label artwork or drawing.

<CCS Answer:> Please see revised label.

Q3. Since the product connects to a PC, in addition to statement from 15.19, the following user manual statements from 15.105 and 15.21 are required. Please provide a revised user manual.

<CCS Answer:> Please see attached revised user manual.

NOTE: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- -- Reorient or relocate the receiving antenna.
- -- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- -- Consult the dealer or an experienced radio/TV technician for help.

Kindest regards,

September

September Radecki

Compliance Certification Services

47173 Benicia Street Fremont, CA 94538

phone: 1-510-771-1090 fax: 1-510-661-0888

September.Radecki@CCSEMC.com < mailto:September.Radecki@CCSEMC.com > Show quoted text -

3 attachments — Download all attachments



HD_musicremote_manual_GM2_SPREADS.pdf

376K <u>View as HTML</u> <u>Download</u>





36K View as HTML

Download

HD_MusicRemote_label_DOCK_GM2_070423.pdf

67K <u>View as HTML Download</u>