Test report No. : 10607274H-C-R1
Page : 94 of 95
Issued date : June 26, 2015
Revised date : July 7, 2015
FCC ID : UJHNR213

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10607274H-C-R1
Page : 95 of 95
Issued date : June 26, 2015
Revised date : July 7, 2015
FCC ID : UJHNR213

Worst Case Position


W52, W53, W56(Horizontal: X-axis/ Vertical:X-axis) W58 (Horizontal: Y-axis/ Vertical:Y-axis)

X-axis



Y-axis

Z-axis



End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124