
Appendix C. Set up Photograph

Spurious Radiation Mode 1



FRONT VIEW

REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C2
Report Issued Date : Aug. 30, 2006
Report Version : Rev.01


Report No.: FG681418-A

Report No. : FG681418-A

Mode 2

FRONT VIEW

REAR VIEW



SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C2
Report Issued Date : Aug. 30, 2006
Report Version : Rev.01