

### Appendix C. Set up Photograph

# Spurious Radiation Model 1



**FRONT VIEW** 



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UJU9QDENIM000 Page No. : C1 of C3
Report Issued Date : Jul. 10, 2007
Report Version : Rev.02

Report No. : FG760116-01A




#### Report No. : FG760116-01A

# Spurious Radiation Model 2



REAR VIEW




#### SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UJU9QDENIM000 Page No. : C2 of C3
Report Issued Date : Jul. 10, 2007
Report Version : Rev.02



#### Report No. : FG760116-01A

# **Spurious Radiation Model 3**



FRONT VIEW

**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UJU9QDENIM000 Page No. : C3 of C3
Report Issued Date : Jul. 10, 2007
Report Version : Rev.02