
Report No. : FR681418

## Appendix C. Set up Photograph

## Conducted Emission

Mode 1~2



**FRONT VIEW** 

**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C5
Report Issued Date : Aug.25, 2006
Report Version : Rev. 01



SIDE VIEW

#### Mode 3




FRONT VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C5
Report Issued Date : Aug.25, 2006
Report Version : Rev. 01





SIDE VIEW

**REAR VIEW** 




SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C5
Report Issued Date : Aug.25, 2006
Report Version : Rev. 01



## **Radiation Emission**

Mode 1-6



**FRONT VIEW** 

**REAR VIEW** 


SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C4 of C5
Report Issued Date : Aug.25, 2006
Report Version : Rev. 01





#### **Mode 7-9**



# FRONT VIEW

### **REAR VIEW**

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255