

Revise note: Previous internal photos have wrong wireless module installed in the device during photo taken.































