Test report No. : 10482807H-A-R1 Page : 28 of 31

Issued date : January 23, 2015
Revised date : February 6, 2015
FCC ID : UUA-A09N2

APPENDIX 3: Photographs of test setup

Conducted emission



Photo 1



Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10482807H-A-R1 Page : 29 of 31

Issued date : January 23, 2015
Revised date : February 6, 2015
FCC ID : UUA-A09N2

Radiated emission



Photo 1



Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

: 10482807H-A-R1 Test report No. Page : 30 of 31 **Issued date** : January 23, 2015 Revised date FCC ID : February 6, 2015 : UUA-A09N2

Worst Case Position

Below 30MHz Z axis

Above 30MHz Horizontal: X-axis / Vertical: X-axis

X-axis



Y-axis



Z-axis



UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 : +81 596 24 8124 Facsimile

Test report No. : 10482807H-A-R1 Page : 31 of 31

Issued date : January 23, 2015
Revised date : February 6, 2015
FCC ID : UUA-A09N2

With/Without Tag



With Tag worst case above 30MHz



Without Tag worst case below 30MHz

End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124