

ROGERS LABS, INC.

4405 West 259th Terrace Louisburg, KS 66053 Phone / Fax (913) 837-3214

February 28, 2008

Timco Engineering Inc. 849 NW State Road 45 Newberry, FL 32669

Applicant: Power Technology, Inc.

16302 Alexander Road Alexander, Ar 72002

Equipment: FCC ID: UW5-900C10908

FCC Rules: Part 2 and 15.249

Gentlemen

Copy of requested information from the project on hold request is shown below.

Based upon our review of this application we have the following questions:

- **1. Block Diagram:** please explain why this document does not indicate the frequency of the oscillator as required by 47 CFR Part 2.1033(b)(5).
- **2. Test Equipment Calibration Due Date:** please verify that the Hp 8562A Spectrum Analyzer shown in the equipment list on page 6 of 25 was in calibration or not used to make these measurements. A due date of 2/2008 is indicated and the date on the test report is 2/21/2008. Alternatively, provide a statement that all test equipment used for this report was in calibration.

Response

- 1. The clock frequencies have been added to the block diagram and the corrected file (Conf BlkDia 900c10908.pdf) uploaded for review.
- 2. The test equipment is maintained and in calibration for testing. This equipment schedule for calibration is February 2008 and scheduled.

Should you require any further information, please contact the undersigned.

Thank you for your consideration in this matter.

Sincerely,

Scot Rogers

Rogers Labs, Inc.

Scot DRogers

Enclosures