

Test report No. : 12992253S-A-R2 Page : 23 of 24 **Issued date** : September 27, 2019 : UY6-TFHM FCC ID

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission



Rear (below 30 MHz Horizontal)





Rear (30 MHz - 1000 MHz)



Rear (Above 1 GHz)



UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN


Telephone: +81 463 50 6400 Facsimile : +81 463 50 6401

Test report No. : 12992253S-A-R2
Page : 24 of 24
Issued date : September 27, 2019
FCC ID : UY6-TFHM

Worst Case Position







End of Report

UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401