Test report No.
 : 12732618S-D-R2


 Page
 : 22 of 23

 Issued date
 : May 30, 2019

 FCC ID
 : UY6-TFHW

## **APPENDIX 3: Photographs of test setup**

## **Radiated emission**



Rear (below 30 MHz Horizontal)




Rear (below 30 MHz Vertical)



Rear (30 MHz - 1000 MHz)



Rear (Above 1 GHz)



UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

 Test report No.
 : 12732618S-D-R2

 Page
 : 23 of 23


 Issued date
 : May 30, 2019

 FCC ID
 : UY6-TFHW

## **Worst Case Position**







**End of Report** 

UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401