## **Doug Noble**

From: Kon Tayfun-QRH473 <tayfun.kon@motorolasolutions.com>

**Sent:** Saturday, August 13, 2011 6:10 AM **Subject:** FX9500 FCC Hopping Sequence

Importance: High

Steve,

Alan told me that FCC is asking for the hopping sequence. Below please find for all FCC modes. Please call me on Monday morning if you need anything else. Thanks,

->setup.sub region=fcc a

 $902300\ 911900\ 905500\ 908700\ 902500\ 912100\ 905700\ 908900\ 902700\ 905900\ 909100\ 902900\ 906100\ 909300\ 903100\ 906300\ 909500\ 903300\ 906500\ 909700\ 903500\ 906700\ 909900\ 903700\ 906900\ 910100\ 903900\ 907100\ 910300\ 904100\ 907300\ 910500\ 904500\ 907700\ 910900\ 904700\ 907900\ 911100\ 904900\ 908100\ 911300\ 905100\ 908300\ 911500\ 905300\ 908500\ 911700$ 

->setup.sub region=fcc b

910100 919700 913300 916500 910300 919900 913500 916700 910500 913700 916900 910700 913900 917100 910900 914100 917300 911100 914300 917500 911300 914500 917700 911500 914700 917900 911700 914900 918100 911900 915100 918300 912100 915300 918500 912300 915500 918700 915700 918900 912700 915900 919100 912900 916100 919300 913100 916300 919500

->setup.sub region=fcc c

917900 927500 921100 924300 918100 927700 921300 924500 918300 921500 924700 918500 921700 924900 918700 921900 925100 918900 922100 925300 919100 922300 925500 919300 922500 925700 919500 922700 925900 919700 922900 926100 919900 923100 926300 920100 923300 926500 920300 923500 926700 920500 923700 926900 920700 923900 927100 920900 924100 927300

->setup.sub\_region=fcc\_dense

902750 926750 910750 918750 903250 927250 911250 919250 903750 911750 919750 904250 912250 920250 904750 912750 920750 905250 913250 921250 905750 913750 921750 906250 914250 922250 906750 914750 922750 907250 915250 923250 907750 915750 923750 908250 916250 924250 908750 916750 924750 909250 917250 925250 909750 917750 925750 910250 918250 926250

Tayfun Kon, PMP, ASQ SSGB

Sr. Program Manager | Motorola Solution - RFID Division | 919-917 6322