



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 421 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 -Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 -Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 422 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 423 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 -Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 -Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 424 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 425 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 426 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 427 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 428 of 812 Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 429 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 430 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 431 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 -




Conducted Output Power on 802.11n (BW 40MHz) Channel 54 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 432 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 -



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 433 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 434 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 435 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 -Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 -Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 436 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain A+B(B)



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 437 of 812 Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 -Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 -Chain B



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6

Page Number : 438 of 812 Report Issued Date: May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05




Conducted Output Power on 802.11n (BW 40MHz) Channel 110 -

Report No.: FR092308-08





Conducted Output Power on 802.11n (BW 40MHz) Channel 110 -Chain A+B(B)



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6

Page Number : 439 of 812 Report Issued Date: May 17, 2012


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 -



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 440 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 441 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05




<Antenna 1 for 3.3V>

Conducted Output Power on 802.11a Channel 52 - Chain A



Conducted Output Power on 802.11a Channel 52 - Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 442 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 52 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 52 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 443 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 60 - Chain A




Conducted Output Power on 802.11a Channel 60 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 444 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 60 - Chain A+B(A)



Conducted Output Power on 802.11a Channel 60 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 445 of 812
Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 64 - Chain A




Conducted Output Power on 802.11a Channel 64 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 446 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05





Conducted Output Power on 802.11a Channel 64 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 447 of 812
Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 100 - Chain A




Conducted Output Power on 802.11a Channel 100 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 448 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 100 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 100 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 449 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 116 - Chain A



Conducted Output Power on 802.11a Channel 116 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 450 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 116 - Chain A+B(A)



Conducted Output Power on 802.11a Channel 116 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 451 of 812
Report Issued Date : May 17, 2012


Report No.: FR092308-08

Report Version : Rev. 05






Conducted Output Power on 802.11a Channel 140 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 452 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 140 - Chain A+B(A)



Conducted Output Power on 802.11a Channel 140 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 453 of 812
Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 -Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 -Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 454 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain A+B(B)



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 455 of 812 Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 456 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain A+B(B)




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 457 of 812 Report Issued Date : May 17, 2012


Report No.: FR092308-08



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 458 of 812 Report Issued Date : May 17, 2012


Report No.: FR092308-08



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain A+B(B)



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 459 of 812
Report Issued Date : May 17, 2012

Report No.: FR092308-08




Report No.: FR092308-08

Conducted Output Power on 802.11n (BW 20MHz) Channel 100 -Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 -Chain B



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6

Page Number : 460 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05




Report No.: FR092308-08

Conducted Output Power on 802.11n (BW 20MHz) Channel 100 -Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 -Chain A+B(B)




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 461 of 812 Report Issued Date: May 17, 2012



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 -Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6

Page Number : 462 of 812 Report Issued Date: May 17, 2012


Report No.: FR092308-08



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 463 of 812 Report Issued Date : May 17, 2012

Report No.: FR092308-08




Report No.: FR092308-08

Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 464 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05




Report No. : FR092308-08

Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 465 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 - Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 466 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 - Chain A+B(B)




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 467 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05




Report No.: FR092308-08

Conducted Output Power on 802.11n (BW 40MHz) Channel 62 -Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 -Chain B



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6

Page Number : 468 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05




Report No.: FR092308-08

Conducted Output Power on 802.11n (BW 40MHz) Channel 62 -Chain A+B(A)



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 -Chain A+B(B)




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 469 of 812 Report Issued Date: May 17, 2012 : Rev. 05 Report Version



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 470 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 -




Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 471 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 -Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 -Chain B



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 472 of 812 Report Issued Date: May 17, 2012

Report No.: FR092308-08




Conducted Output Power on 802.11n (BW 40MHz) Channel 110 -

Report No.: FR092308-08



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 - Chain A+B(B)

Copyright 2000-2010 Agilent Technologies




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 473 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05




Test Report No. : FR092308-08

Conducted Output Power on 802.11n (BW 40MHz) Channel 134 - Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 474 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 475 of 812
Report Issued Date : May 17, 2012

Report No.: FR092308-08




<Antenna 2 for 4.5V>

Conducted Output Power on 802.11a Channel 52 - Chain A



Conducted Output Power on 802.11a Channel 52 - Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 476 of 812
Report Issued Date : May 17, 2012


Report No.: FR092308-08



Conducted Output Power on 802.11a Channel 52 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 52 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 477 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 60 - Chain A




Conducted Output Power on 802.11a Channel 60 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 478 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 60 - Chain A+B(A)



Conducted Output Power on 802.11a Channel 60 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 479 of 812
Report Issued Date : May 17, 2012

Report No.: FR092308-08




Report No. : FR092308-08

Conducted Output Power on 802.11a Channel 64 - Chain A



Conducted Output Power on 802.11a Channel 64 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 480 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 64 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 64 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 481 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 100 - Chain A




Conducted Output Power on 802.11a Channel 100 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 482 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 100 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 100 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 483 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 116 - Chain A




Conducted Output Power on 802.11a Channel 116 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 484 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 116 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 116 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 485 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 140 - Chain A



Conducted Output Power on 802.11a Channel 140 - Chain B



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 486 of 812 Report Issued Date: May 17, 2012

Report No.: FR092308-08


: Rev. 05 Report Version



Conducted Output Power on 802.11a Channel 140 - Chain A+B(A)



Conducted Output Power on 802.11a Channel 140 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 487 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05




Report No.: FR092308-08

Conducted Output Power on 802.11n (BW 20MHz) Channel 52 -Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 -Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 488 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain A+B(B)




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 489 of 812 Report Issued Date : May 17, 2012


Report No.: FR092308-08



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 490 of 812
Report Issued Date : May 17, 2012


Report No.: FR092308-08



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain A+B(B)




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 491 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05




Report No.: FR092308-08

Conducted Output Power on 802.11n (BW 20MHz) Channel 64 -Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 -Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 492 of 812 Report Issued Date: May 17, 2012



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain A+B(B)



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 493 of 812 Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 494 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain A+B(B)



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 495 of 812 Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 -Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 -Chain B



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 496 of 812 Report Issued Date: May 17, 2012

Report Version : Rev. 05




est Report Report No.: FR092308-08

Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain A+B(B)




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 497 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05




Test Report No. : FR092308-08

Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 498 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 499 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 -



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 500 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 -




Conducted Output Power on 802.11n (BW 40MHz) Channel 54 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 501 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 -Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 -Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 502 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 503 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 -Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 -Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 504 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 505 of 812 Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 - Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 506 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 507 of 812
Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 - Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 - Chain B



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 508 of 812 Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 - Chain A+B(B)




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 509 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05




<Antenna 2 for 3.3V>

Conducted Output Power on 802.11a Channel 52 - Chain A



Conducted Output Power on 802.11a Channel 52 - Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 510 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 52 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 52 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 511 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 60 - Chain A




Conducted Output Power on 802.11a Channel 60 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 512 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 60 - Chain A+B(A)



Conducted Output Power on 802.11a Channel 60 - Chain A+B(B)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 513 of 812 Report Issued Date: May 17, 2012

Report No.: FR092308-08


: Rev. 05 Report Version



Conducted Output Power on 802.11a Channel 64 - Chain A




Conducted Output Power on 802.11a Channel 64 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 514 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 64 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 64 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 515 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 100 - Chain A




Conducted Output Power on 802.11a Channel 100 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 516 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 100 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 100 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 517 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 116 - Chain A




Conducted Output Power on 802.11a Channel 116 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 518 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 116 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 116 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 519 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 140 - Chain A




Conducted Output Power on 802.11a Channel 140 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 520 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 140 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 140 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 521 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 522 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 523 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 -Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 -Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 524 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 525 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 526 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 527 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 528 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 -Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 -Chain A+B(B)




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 529 of 812 Report Issued Date: May 17, 2012 : Rev. 05 Report Version



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 530 of 812
Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 531 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 532 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 533 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 - Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 534 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 -



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 535 of 812 Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 536 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain A+B(A)




Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 537 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 538 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 539 of 812 Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 -



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 -Chain B



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 540 of 812 Report Issued Date: May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 541 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 -Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 -Chain B



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6

Page Number : 542 of 812 Report Issued Date: May 17, 2012


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 -



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 - Chain A+B(B)




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 543 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05




<Antenna 3 for 4.5V>

Conducted Output Power on 802.11a Channel 52 - Chain A



Conducted Output Power on 802.11a Channel 52 - Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 544 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 52 - Chain A+B(A)



Conducted Output Power on 802.11a Channel 52 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 545 of 812
Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 60 - Chain A




Conducted Output Power on 802.11a Channel 60 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 546 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05





Conducted Output Power on 802.11a Channel 60 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6

Page Number : 547 of 812 Report Issued Date: May 17, 2012


: Rev. 05 Report Version



Conducted Output Power on 802.11a Channel 64 - Chain A




Conducted Output Power on 802.11a Channel 64 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 548 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 64 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 64 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 549 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 100 - Chain A




Conducted Output Power on 802.11a Channel 100 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 550 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 100 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 100 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 551 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 116 - Chain A




Conducted Output Power on 802.11a Channel 116 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 552 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 116 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 116 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 553 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 140 - Chain A




Conducted Output Power on 802.11a Channel 140 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 554 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 140 - Chain A+B(A)



Conducted Output Power on 802.11a Channel 140 - Chain A+B(B)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 555 of 812 Report Issued Date: May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 556 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 557 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 558 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05




Test Report No.: FR092308-08

Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain A+B(B)




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 559 of 812 Report Issued Date : May 17, 2012


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain B



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 560 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05