



Single File Photographs_Internal

EUT 1

Model: AP-8533I








SPORTON LAB.

Report No.: 592302-05







SPORTON LAB.

Report No.: 592302-05





Report No.: 592302-05



SPORTON International Inc.

TEL : 886-3-327-3456


FAX : 886-3-327-0973

PAGE NUMBER : 5 of 33

ISSUED DATE : Feb. 02, 2016



Report No.: 592302-05



SPORTON International Inc.

TEL : 886-3-327-3456

FAX : 886-3-327-0973



PAGE NUMBER : 6 of 33

ISSUED DATE : Feb. 02, 2016



SPURTON LAB.

Report No.: 592302-05












Report No.: 592302-05












Report No.: 592302-05







Report No.: 592302-05







Report No.: 592302-05








Report No.: 592302-05






Report No.: 592302-05








Report No.: 592302-05






Report No.: 592302-05







Report No.: 592302-05




SPORTON International Inc.



TEL : 886-3-327-3456



FAX : 886-3-327-0973

PAGE NUMBER : 22 of 33

ISSUED DATE : Feb. 02, 2016












Report No.: 592302-05






Report No.: 592302-05







Report No.: 592302-05







Report No.: 592302-05







Report No.: 592302-05



EUT 2


Model: AP-8533I





Report No.: 592302-05











Report No.: 592302-05

Single File Antenna_Photographs








Report No.: 592302-05






Report No.: 592302-05









Report No.: 592302-05






SPURTON LAB.

Report No.: 592302-05





Report No.: 592302-05





Report No.: 592302-05






Report No.: 592302-05







Report No.: 592302-05





SPURTON LAB.

Report No.: 592302-05







Report No.: 592302-05








Report No.: 592302-05







Report No.: 592302-05









Report No.: 592302-05





SPURTON LAB.

Report No.: 592302-05



SPURTON International Inc.

TEL : 886-3-327-3456

FAX : 886-3-327-0973

PAGE NUMBER : 17 of 19

ISSUED DATE : Feb. 02, 2016



Report No.: 592302-05

