

Appendix D. Duty Cycle Plots


| Antenna | Band | Duty Cycle(%) | T(us) | 1/T(kHz) | VBW Setting |
|-------------------|---------------------|---------------|-------|----------|-------------|
| 1 | 802.11a | 94.95 | 2070 | 0.48 | 1kHz |
| 2 | 802.11a | 94.95 | 2070 | 0.48 | 1kHz |
| MIMO Ant. 1+2 (1) | 802.11a | 95.39 | 2070 | 0.48 | 1kHz |
| MIMO Ant. 1+2 (2) | 802.11a | 95.39 | 2070 | 0.48 | 1kHz |
| 1 | 5GHz 802.11n HT20 | 95.01 | 1935 | 0.52 | 1kHz |
| 2 | 5GHz 802.11n HT20 | 94.61 | 1930 | 0.52 | 1kHz |
| MIMO Ant. 1+2 (1) | 5GHz 802.11n HT20 | 95.07 | 1930 | 0.52 | 1kHz |
| MIMO Ant. 1+2 (2) | 5GHz 802.11n HT20 | 95.07 | 1930 | 0.52 | 1kHz |
| 1 | 5GHz 802.11n HT40 | 90.39 | 940 | 1.06 | 3kHz |
| 2 | 5GHz 802.11n HT40 | 90.48 | 950 | 1.05 | 3kHz |
| MIMO Ant. 1+2 (1) | 5GHz 802.11n HT40 | 90.48 | 950 | 1.05 | 3kHz |
| MIMO Ant. 1+2 (2) | 5GHz 802.11n HT40 | 90.48 | 950 | 1.05 | 3kHz |
| 1 | 5GHz 802.11ac VHT20 | 95.10 | 1940 | 0.52 | 1kHz |
| 2 | 5GHz 802.11ac VHT20 | 94.63 | 1940 | 0.52 | 1kHz |
| MIMO Ant. 1+2 (1) | 5GHz 802.11ac VHT20 | 95.10 | 1940 | 0.52 | 1kHz |
| MIMO Ant. 1+2 (2) | 5GHz 802.11ac VHT20 | 95.57 | 1940 | 0.52 | 1kHz |
| 1 | 5GHz 802.11ac VHT40 | 90.57 | 960 | 1.04 | 3kHz |
| 2 | 5GHz 802.11ac VHT40 | 90.57 | 960 | 1.04 | 3kHz |
| MIMO Ant. 1+2 (1) | 5GHz 802.11ac VHT40 | 91.43 | 960 | 1.04 | 3kHz |
| MIMO Ant. 1+2 (2) | 5GHz 802.11ac VHT40 | 91.43 | 960 | 1.04 | 3kHz |
| 1 | 5GHz 802.11ac VHT80 | 86.71 | 600 | 1.67 | 3kHz |
| 2 | 5GHz 802.11ac VHT80 | 86.71 | 600 | 1.67 | 3kHz |
| MIMO Ant. 1+2 (1) | 5GHz 802.11ac VHT80 | 86.71 | 600 | 1.67 | 3kHz |
| MIMO Ant. 1+2 (2) | 5GHz 802.11ac VHT80 | 86.21 | 600 | 1.67 | 3kHz |

TEL: 886-3-327-3456 FAX: 886-3-328-4978 Report No.: FR661812F



<Ant. 1>






Date: 30.JUN.2016 11:42:58

<SISO Ant. 1>

802.11n HT20




Date: 30.JUN.2016 13:57:29




Test Report No. : FR661812F





Date: 30.JUN.2016 14:37:55


802.11ac VHT20



Date: 30.JUN.2016 15:23:56




802.11ac VHT40



Date: 30.JUN.2016 16:48:53

802.11ac VHT80




Date: 30.JUN.2016 18:08:29



<Ant. 2>


802.11a



Date: 30.JUN.2016 11:49:53

<SISO Ant. 2>

802.11n HT20




Date: 30.JUN.2016 14:04:27

TEL: 886-3-327-3456 FAX: 886-3-328-4978 Report No.: FR661812F








Date: 30.JUN.2016 14:47:45


802.11ac VHT20



Date: 30.JUN.2016 15:40:45




802.11ac VHT40



Date: 30.JUN.2016 17:01:40


802.11ac VHT80



Date: 30.JUN.2016 18:25:26


FCC RF Test Report

<MIMO Ant. 1+2 (1)> 802.11a



Date: 27.JUN.2016 09:43:21

802.11n HT20



Date: 27.JUN.2016 13:54:46

TEL: 886-3-327-3456 FAX: 886-3-328-4978


Page Number

: D8 of D13

Report No.: FR661812F








Date: 27.JUN.2016 16:31:47


802.11ac VHT20



Date: 27.JUN.2016 17:57:19




802.11ac VHT40



Date: 27.JUN.2016 18:04:24

802.11ac VHT80



Date: 30.JUN.2016 19:10:14

TEL: 886-3-327-3456 FAX: 886-3-328-4978


Page Number

: D10 of D13




FCC RF Test Report No.: FR661812F

<MIMO Ant. 1+2 (2)> 802.11a



Date: 27.JUN.2016 09:44:05


802.11n HT20



Date: 27.JUN.2016 13:55:32








Date: 27.JUN.2016 16:32:38


802.11ac VHT20



Date: 27.JUN.2016 17:57:58




802.11ac VHT40



Date: 27.JUN.2016 18:03:07

802.11ac VHT80



Date: 30.JUN.2016 19:10:50