

## Report No.: FA141402

## Appendix D. Test Setup Photos



Left Tilted (DUT with Scanner 1)




Left Tilted (DUT with Scanner 2)




Front of the DUT with Phantom 1.5 cm Gap (DUT with Scanner 2)



Front of the DUT with Phantom 0 cm Gap (DUT with Scanner 2 and Rigid Holster)



Back of the DUT with Phantom 1.5 cm Gap (DUT with Scanner 1)



Back of the DUT with Phantom 1.5 cm Gap (DUT with Scanner 2)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC55N0 Page Number : D1 of D3
Report Issued Date : Aug. 09, 2011
Report Version : Rev. 02



## FCC SAR Test Report



Back of the DUT with Phantom 0 cm Gap (DUT with Scanner 2 and Soft Holster)

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC55N0 Page Number : D2 of D3
Report Issued Date : Aug. 09, 2011
Report Version : Rev. 02

Report No. : FA141402



Report No.: FA141402

## **Antenna Location:**



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC55N0 Page Number : D3 of D3
Report Issued Date : Aug. 09, 2011
Report Version : Rev. 02