



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain A+B(B)




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 561 of 812
Report Issued Date : May 17, 2012


Report No.: FR092308-08



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 562 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 563 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain A




Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 564 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 565 of 812
Report Issued Date : May 17, 2012


Report No.: FR092308-08



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 -Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 -Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 566 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 -




Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 567 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 -Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 -Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 568 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 569 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 -Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 -Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 570 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain A+B(A)




Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 571 of 812
Report Issued Date : May 17, 2012



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 -



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 572 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 573 of 812 Report Issued Date : May 17, 2012


Report No.: FR092308-08



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 - Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 574 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 -



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 575 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 -Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 -Chain B



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6

Page Number : 576 of 812 Report Issued Date: May 17, 2012




Conducted Output Power on 802.11n (BW 40MHz) Channel 134 -

Report No.: FR092308-08



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 - Chain A+B(B)




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 577 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05




<Antenna 3 for 3.3V>

Conducted Output Power on 802.11a Channel 52 - Chain A



Conducted Output Power on 802.11a Channel 52 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 578 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 52 - Chain A+B(A)



Conducted Output Power on 802.11a Channel 52 - Chain A+B(B)




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 579 of 812
Report Issued Date : May 17, 2012


Report No.: FR092308-08



Conducted Output Power on 802.11a Channel 60 - Chain A




Conducted Output Power on 802.11a Channel 60 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 580 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 60 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 60 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 581 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 64 - Chain A




Conducted Output Power on 802.11a Channel 64 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 582 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 64 - Chain A+B(A)



Conducted Output Power on 802.11a Channel 64 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6

Page Number : 583 of 812 Report Issued Date: May 17, 2012


Report No.: FR092308-08



Conducted Output Power on 802.11a Channel 100 - Chain A




Conducted Output Power on 802.11a Channel 100 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 584 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 100 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 100 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 585 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 116 - Chain A




Conducted Output Power on 802.11a Channel 116 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 586 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 116 - Chain A+B(A)



Conducted Output Power on 802.11a Channel 116 - Chain A+B(B)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 587 of 812 Report Issued Date: May 17, 2012

Report No.: FR092308-08


: Rev. 05 Report Version



Conducted Output Power on 802.11a Channel 140 - Chain A




Conducted Output Power on 802.11a Channel 140 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 588 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 140 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 140 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 589 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 590 of 812 Report Issued Date : May 17, 2012


Report No.: FR092308-08



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 591 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 592 of 812
Report Issued Date : May 17, 2012


Report No.: FR092308-08



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 -Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 -Chain A+B(B)



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6

Page Number : 593 of 812 Report Issued Date: May 17, 2012


: Rev. 05 Report Version



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 594 of 812 Report Issued Date : May 17, 2012


Report No.: FR092308-08



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain A+B(B)




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 595 of 812 Report Issued Date : May 17, 2012


Report No.: FR092308-08



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 596 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain A+B(A)




Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 597 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 598 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 599 of 812 Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 -Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 -Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 600 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 -Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 -Chain A+B(B)




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 601 of 812 Report Issued Date: May 17, 2012 : Rev. 05 Report Version



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 -Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 -Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 602 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 603 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 604 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05




est Report No. : FR092308-08

Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 605 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05




Test Report No. : FR092308-08

Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 606 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain A+B(A)




Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 607 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 - Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 - Chain B



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 608 of 812 Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 -



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 609 of 812
Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 - Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 610 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 -



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 611 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05




<Antenna 4 for 3.3V>

Conducted Output Power on 802.11a Channel 52 - Chain A



Conducted Output Power on 802.11a Channel 52 - Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 612 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 52 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 52 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 613 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 60 - Chain A




Conducted Output Power on 802.11a Channel 60 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 614 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 60 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 60 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 615 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 64 - Chain A




Conducted Output Power on 802.11a Channel 64 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 616 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 64 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 64 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 617 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 100 - Chain A



Conducted Output Power on 802.11a Channel 100 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 618 of 812
Report Issued Date : May 17, 2012


Report No.: FR092308-08

Report Version : Rev. 05






Conducted Output Power on 802.11a Channel 100 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 619 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 116 - Chain A



Conducted Output Power on 802.11a Channel 116 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 620 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 116 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 116 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 621 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 140 - Chain A



Conducted Output Power on 802.11a Channel 140 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 622 of 812
Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 140 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 140 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 623 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 624 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05




est Report Report No.: FR092308-08

Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 625 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 -Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 -Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 626 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 627 of 812 Report Issued Date : May 17, 2012


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 628 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain A+B(B)




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 629 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05




Test Report No. : FR092308-08

Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 630 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 631 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 632 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05




Conducted Output Power on 802.11n (BW 20MHz) Channel 116 -

Report No.: FR092308-08



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 633 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 -Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 -Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 634 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain A+B(B)



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 635 of 812 Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 -



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 636 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 -



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 - Chain A+B(B)



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 637 of 812
Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 638 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain A+B(B)



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 639 of 812 Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain B



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 640 of 812
Report Issued Date : May 17, 2012


Report No.: FR092308-08

Report Version : Rev. 05




Report Report No.: FR092308-08

Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 641 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 -Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 -Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 642 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 -



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 643 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 -



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 644 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 645 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05




<Antenna 5 for 4.5V>

Conducted Output Power on 802.11a Channel 52 - Chain A



Conducted Output Power on 802.11a Channel 52 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 646 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 52 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 52 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 647 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 60 - Chain A



Conducted Output Power on 802.11a Channel 60 - Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 648 of 812 Report Issued Date: May 17, 2012 : Rev. 05 Report Version



Conducted Output Power on 802.11a Channel 60 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 60 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 649 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 64 - Chain A




Conducted Output Power on 802.11a Channel 64 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 650 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 64 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 64 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 651 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 100 - Chain A



Conducted Output Power on 802.11a Channel 100 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 652 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 100 - Chain A+B(A)



Conducted Output Power on 802.11a Channel 100 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 653 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 116 - Chain A




Conducted Output Power on 802.11a Channel 116 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 654 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 116 - Chain A+B(A)



Conducted Output Power on 802.11a Channel 116 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 655 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 140 - Chain A




Conducted Output Power on 802.11a Channel 140 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 656 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05






Conducted Output Power on 802.11a Channel 140 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 657 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 658 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain A+B(B)



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 659 of 812 Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 660 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 661 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 -Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 -Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 662 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 663 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain B



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 664 of 812
Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain A+B(B)



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 665 of 812 Report Issued Date : May 17, 2012


Report No.: FR092308-08

Report Version : Rev. 05




Conducted Output Power on 802.11n (BW 20MHz) Channel 116 -

Report No.: FR092308-08



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 666 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain A+B(A)




Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 667 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 668 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05




Port Report No. : FR092308-08

Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 140 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 669 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 - Chain A




Conducted Output Power on 802.11n (BW 40MHz) Channel 54 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 670 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 -



Conducted Output Power on 802.11n (BW 40MHz) Channel 54 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 671 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 -Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 -Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 672 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 40MHz) Channel 62 - Chain A+B(B)



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 673 of 812 Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 -




Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 674 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain A+B(A)




Conducted Output Power on 802.11n (BW 40MHz) Channel 102 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 675 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 -Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 110 -Chain B



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 676 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05




Conducted Output Power on 802.11n (BW 40MHz) Channel 110 -

Report No.: FR092308-08





Conducted Output Power on 802.11n (BW 40MHz) Channel 110 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 677 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 -Chain A



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 -Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 678 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 40MHz) Channel 134 - Chain A+B(B)




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 679 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05




<Antenna 5 for 3.3V>

Conducted Output Power on 802.11a Channel 52 - Chain A



Conducted Output Power on 802.11a Channel 52 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 680 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 52 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 52 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 681 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 60 - Chain A




Conducted Output Power on 802.11a Channel 60 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 682 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 60 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 60 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 683 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 64 - Chain A




Conducted Output Power on 802.11a Channel 64 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 684 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05





Conducted Output Power on 802.11a Channel 64 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 685 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 100 - Chain A




Conducted Output Power on 802.11a Channel 100 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 686 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 100 - Chain A+B(A)



Conducted Output Power on 802.11a Channel 100 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 687 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 116 - Chain A




Conducted Output Power on 802.11a Channel 116 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 688 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 116 - Chain A+B(A)



Conducted Output Power on 802.11a Channel 116 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 689 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 140 - Chain A




Conducted Output Power on 802.11a Channel 140 - Chain B




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 690 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11a Channel 140 - Chain A+B(A)




Conducted Output Power on 802.11a Channel 140 - Chain A+B(B)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 691 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 - Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 692 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05




Conducted Output Power on 802.11n (BW 20MHz) Channel 52 -

Report No.: FR092308-08



Conducted Output Power on 802.11n (BW 20MHz) Channel 52 -Chain A+B(B)

Copyright 2000-2007 Agilent Technologies



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6

Page Number : 693 of 812 Report Issued Date: May 17, 2012


: Rev. 05 Report Version



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain B




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 694 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 -



Conducted Output Power on 802.11n (BW 20MHz) Channel 60 - Chain A+B(B)



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 695 of 812
Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 -Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 -Chain B




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6


Page Number : 696 of 812 Report Issued Date: May 17, 2012 Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 64 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 697 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain B



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 698 of 812 Report Issued Date : May 17, 2012

Report No.: FR092308-08


Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain A+B(A)



Conducted Output Power on 802.11n (BW 20MHz) Channel 100 - Chain A+B(B)




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 699 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain A



Conducted Output Power on 802.11n (BW 20MHz) Channel 116 - Chain B



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : 700 of 812
Report Issued Date : May 17, 2012
Report Version : Rev. 05