


Appendix D. Product Photos



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-C325 Page Number : D1 of D1
Report Issued Date : Sep. 16, 2009
Report Version : Rev. 01

Report No.: FA982031



Report No.: FA982031

Appendix E. Test Setup Photos



USB Configuration 1 (Horizontal Up with Phantom 0.5 cm Gap)



USB Configuration 2 (Horizontal Down with Phantom 0.5 cm Gap)



USB Configuration 3 (Vertical Front with Phantom 0.5 cm Gap)



USB Configuration 4 (Vertical Back with Phantom 0.5 cm Gap)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-C325 Page Number : E1 of E2
Report Issued Date : Aug. 27, 2009
Report Version : Rev. 01





USB Configuration 1 (Horizontal Up with Phantom 1.0 cm Gap)




Report No.: FA982031

USB Configuration 1 (Horizontal Up with Phantom 1.5 cm Gap)



USB Configuration 2 (Horizontal Down with Phantom 1.0 cm Gap)



USB Configuration 2 (Horizontal Down with Phantom 1.5 cm Gap)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZI-C325

: E2 of E2 Page Number Report Issued Date: Aug. 27, 2009 Report Version : Rev. 01