

Test Report No.: 10866733S-A


## **APPENDIX 3: Photographs of test setup**


#### **Radiated emission**





(rear, below 30MHz)





(rear, 30MHz to 1GHz)


(rear, above 1GHz)

#### UL Japan, Inc. **Shonan EMC Lab.**

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401

Test Report No.: 10866733S-A


#### Pre-check of the worst position



X-axis



Y-axis



Z-axis


### UL Japan, Inc. **Shonan EMC Lab.**

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401

Test Report No.: 10866733S-A

#### **Antenna terminal conducted tests**





# **End of Report**

#### UL Japan, Inc. **Shonan EMC Lab.**

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN Telephone : +81 463 50 6400

Facsimile +81 463 50 6401