

AT4 wireless, S.A.U. Parque Tecnológico de Andalucía C/ Severo Ochoa 2 & 6 29590 Campanillas Málaga, España

Date: 01/02/2017

REF: Declaration about Tune-up info & test reports applicable to LLC7262 (FCC ID: VBO-LLC7262, IC:

135Y-LLC7262)

Dear Sir / Madam:

Philips Lighting North America Corporation hereby declares that product Philips LLC7262 with FCC ID: VBO-LLC7262 and IC: 135Y-LLC7262 integrates the Sierra Wireless GPRS AirPrime Embedded Module HL8548 with FCC ID: N7NHL8548 and IC: 2417C-HL8548. This module has not been modified and has been integrated following module's manufacturer instructions (installation, extreme voltages, temperatures, etc).

The Test Reports supplied by Sierra Wireless for our submission remain applicable, valid and representative of HL8548 manufactured today and are representative for the certification of the Outdoor Luminaire Controllers Philips LLC7262.

Since nothing has been changed in the RF part and simply have integrated the module in our product, being the communication done by the module's connectivity, the following test results of the module are valid, applicable and representative for the compliance of these products:

Test report Part 22H & 24E and RSS-132 & RSS-133 (T140716W05-RP)

Furthermore, as said above, the HL8548 module's tune-up info is also representative for the Philips LLC7262.

As verification of the compliance of the device, the following testing has been performed for the host:

- Radiated Spurious Emissions

Sincerely,

P.A.

By: Raymond Spiewak Title: Quality manager

Company: Philips Lighting North America Corporation

Telephone: 781-418-9380

e-mail: raymond.spiewak@philips.com