Test report No. : 10523242H-A-R1
Page : 66 of 69
Issued date : October 22, 2014
Revised date : November 7, 2014
FCC ID : VIYHRM1034

APPENDIX 3: Photographs of test setup

<u>Conducted Emission</u> [Host device: Stereo Speaker]



Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10523242H-A-R1 Page : 67 of 69

Issued date : October 22, 2014
Revised date : November 7, 2014
FCC ID : VIYHRM1034

Radiated Spurious Emission [Host device: Stereo Speaker]



Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10523242H-A-R1 Page : 68 of 69

Issued date : October 22, 2014
Revised date : November 7, 2014
FCC ID : VIYHRM1034

Radiated Spurious Emission [Host device: AV Receiver]




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10523242H-A-R1
Page : 69 of 69
Issued date : October 22, 2014
Revised date : November 7, 2014
FCC ID : VIYHRM1034

Worst Case Position

[Host device: Stereo Speaker]

Above 1GHz (Horizontal: X-axis/ Vertical: Y-axis) Below 1GHz (Horizontal: X-axis/ Vertical: X-axis)







End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN