Test report No. : 11204390H-B-R2
Page : 32 of 33
Issued date : April 19, 2016
Revised date : May 19, 2016
FCC ID : VIYHRM5072

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1



Photo 2


UL Japan, Inc. Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

: 11204390H-B-R2 Test report No. Page : 33 of 33 : April 19, 2016 **Issued date** : May 19, 2016 Revised date FCC ID : VIYHRM5072

Worst Case Position
Below 1 GHz (Horizontal: X-axis/ Vertical: X-axis) Above 1 GHz (Horizontal: Y-axis/ Vertical: Z-axis)







End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile : +81 596 24 8124