Test report No. : 33BE0216-HO-01-A-R1

Page : 27 of 28

Issued date : November 14, 2012 Revised date : November 21, 2012 FCC ID : VIYARC0517

# **APPENDIX 3: Photographs of test setup**

### **Radiated Spurious Emission**



Photo 1



Photo 2

### UL Japan, Inc.

#### **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 33BE0216-HO-01-A-R1


Page : 28 of 28

Issued date : November 14, 2012 Revised date : November 21, 2012 FCC ID : VIYARC0517

## Worst Case Position (Horizontal: X-axis/ Vertical: Y-axis)







### **End of Report**

### UL Japan, Inc.

**Head Office EMC Lab.** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124