Test report No. : 10105410H-B Page : 32 of 33

Issued date : November 29, 2013 FCC ID : VIYARC0557

## **APPENDIX 3: Photographs of test setup**

# **Radiated Spurious Emission**




Photo 1




Photo 2

# UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10105410H-B Page : 33 of 33


Issued date : November 29, 2013 FCC ID : VIYARC0557

# Worst Case Position (Horizontal: X-axis/ Vertical: Z-axis)

## X-axis



Y-axis



**Z**-axis



**End of Report** 

**Head Office EMC Lab.** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124