

American Certification Body Inc. 6731 Whittier Ave, Suite C110, McLean, VA 22101, USA

ACB:

Thanks for uploading photos of the device, internal and external.

I notice you have re-uploaded the old photos from the original project. Are there new photos which apply to this modified device?

Also, for all hardware changes to a certified device, please provide any changed technical documentation, such as the circuit diagrams.

Aviat:

The certified device has not changed at all. It is only the fact that we allow the device to be used with a slightly different modem that has prompted the permissive change.

The modem is a plug-in card within the indoor unit. RAC LL has a slightly different modem from RAC 60 and we have now tested with both RACs. The modem is not in the radio unit and was remotely located in a control room during testing of the radio device. The also test the modem equipment to Part 15B.

The certified radio device has not changed. The circuit diagrams for the certified radio device have also not changed.