


Report No. : FR192719

Appendix A. Test Photos





Transmitter Radiated Spurious Emissions (Below 1GHz)



SPORTON INTERNATIONAL INC.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 75 of 79 Report Version : Rev. 01 FCC ID

VKV-F36N






Report No. : FR192719

Transmitter Radiated Spurious Emissions (Above 1GHz)



Transmitter Radiated Spurious Emissions (Above 1GHz)



SPORTON INTERNATIONAL INC.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 76 of 79 Report Version : Rev. 01 FCC ID

VKV-F36N



FCC Test Report

Report No. : FR192719



SPORTON INTERNATIONAL INC.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255
 Page No.
 : 77 of 79

 Report Version
 : Rev. 01

 FCC ID
 VKV-F36N





Report No. : FR192719

AC Line Conducted Emissions



AC Line Conducted Emissions



SPORTON INTERNATIONAL INC.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 78 of 79 Report Version : Rev. 01

FCC ID VKV-F36N