Test Report No.: 10009791S-A

APPENDIX 3: Photographs of test setup

Conducted emission










UL Japan, Inc. **Shonan EMC Lab.**

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile +81 463 50 6401


Test Report No.: 10009791S-A

Radiated emission



Rear 9kHz-30MHz







UL Japan, Inc. Shonan EMC Lab.


1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401


Test Report No.: 10009791S-A

Pre-check of the worst position

RFID Module with tag X-axis



RFID Module without tag
X-axis











END OF REPORT

UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401