



## Appendix C. Photographs of Setup

## **Conducted Emission**

Mode 1,2 and 4



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page No. : C1 of C4
Report Issued Date : Oct. 31, 2007
Report Version : Rev. 01

Report No. : FR751505-03



SIDE VIEW

## Mode 3




FRONT VIEW

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page No. : C2 of C4
Report Issued Date : Oct. 31, 2007
Report Version : Rev. 01





**REAR VIEW** 



SIDE VIEW


SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page No. : C3 of C4
Report Issued Date : Oct. 31, 2007
Report Version : Rev. 01

Report No. : FR751505-03

## **Radiation Emission**

Mode 1-6



FRONT VIEW

**REAR VIEW** 

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page No. : C4 of C4
Report Issued Date : Oct. 31, 2007
Report Version : Rev. 01