Test report No. : 31HE0184-HO-02

: 12 of 60 : July 11, 2011 : VPYLBQX466 Page Issued date FCC ID

APPENDIX 1: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 31HE0184-HO-02

Page : 13 of 60 Issued date : July 11, 2011 FCC ID : VPYLBQX466

Radiated Spurious Emission



Photo 1




Photo 2

UL Japan, Inc.

Head Office EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124


Test report No. : 31HE0184-HO-02
Page : 14 of 60
Issued date : July 11, 2011
FCC ID : VPYLBQX466

Worst Case Position (Horizontal: X-axis/ Vertical: Y-axis)


X-axis



Y-axis



Z-axis



4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124