Test report No. : 10044596H-A
Page : 18 of 20
Issued date : August 20, 2013
FCC ID : VPYLBXN604

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission



Photo 1




Photo 2


UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10044596H-A
Page : 19 of 20
Issued date : August 20, 2013
FCC ID : VPYLBXN604

Worst Case Position (Horizontal: X-axis/ Vertical: Y-axis)



UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

^{*}The module and antenna will be mounted on a jig board with the same specification as the one used for testing, and it will be installed in the end product.


Test report No. : 10044596H-A
Page : 20 of 20
Issued date : August 20, 2013
FCC ID : VPYLBXN604

Antenna Pattern Length

[3mm length]



[50mm length]



End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124