Test report No. : 10059672H-A-R1 Page : 38 of 40

Page : 38 of 40
Issued date : October 29, 2013
Revised date : November 12, 2013
FCC ID : LBWA1ZZYM6

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10059672H-A-R1

Page : 39 of 40

Issued date : October 29, 2013
Revised date : November 12, 2013
FCC ID : LBWA1ZZYM6

Radiated Spurious Emission



Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10059672H-A-R1


Page : 40 of 40
Issued date : October 29, 2013
Revised date : November 12, 2013
FCC ID : LBWA1ZZYM6

Worst Case Position (Horizontal: X-axis/ Vertical: Z-axis)


X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124