Test report No. : 10009666H-A-R2
Page : 39 of 41
Issued date : May 27, 2013
Revised date : June 10, 2013
FCC ID : VPYLBYR650

### **APPENDIX 3: Photographs of test setup**

#### **Conducted Emission**



Photo 1



Photo 2

### UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10009666H-A-R2
Page : 40 of 41
Issued date : May 27, 2013
Revised date : June 10, 2013
FCC ID : VPYLBYR650

# **Radiated Spurious Emission**



Photo 1



Photo 2

#### UL Japan, Inc. Head Office EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10009666H-A-R2
Page : 41 of 41
Issued date : May 27, 2013
Revised date : June 10, 2013
FCC ID : VPYLBYR650

# **Worst Case Position**

Module (Horizontal: X-axis/ Vertical: X-axis) Antenna (Horizontal: X-axis/ Vertical: Z-axis)



**End of Report** 

#### UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124