Test report No. : 11119465H-A-R1
Page : 46 of 48
Issued date : February 8, 2016
Revised date : March 8, 2016
FCC ID : VPYLB1CA

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 11119465H-A-R1 Page : 47 of 48

Issued date : February 8, 2016
Revised date : March 8, 2016
FCC ID : VPYLB1CA

Radiated Spurious Emission




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124


Test report No. : 11119465H-A-R1
Page : 48 of 48
Issued date : February 8, 2016
Revised date : March 8, 2016
FCC ID : VPYLB1CA

Worst Case Position (Horizontal: Z-axis/ Vertical: Y-axis)


X-axis



Y-axis



Z-axis



End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124