FCC ID : VPYLB1LD IC CN : 772C-LB1LD

ANNEX

 Report No. : 17040026JMA-002
 Original: April 20, 2017

 FCC ID : VPYLB1LD
 Revised: May 2, 2017

FCC ID : VPYLB1LD IC CN : 772C-LB1LD

A. HARD COPY OF SPECTRUM PLOTS

FJP-TE029 / Effective Date: 23 Jul 2010

FCC ID : VPYLB1LD IC CN : 772C-LB1LD

A.1 20 dB Bandwidth and 99 % Occupied Bandwidth

Report No.: 17040026JMA-002


FCC ID: VPYLB1LD IC CN: 772C-LB1LD


DH5 2402 MHz Ref -10.00 dBm Span 5 MHz Sweep 7.333 ms #VBW 91 kHz -4.67 dBm 912.51 kHz Transmit Freq Error -1.772 kHz **OBW Power** 99.00 % 992.0 kHz


2441 MHz



2480 MHz









Original: April 20, 2017

Revised: May 2, 2017


2441 MHz




2480 MHz



FCC ID: VPYLB1LD IC CN: 772C-LB1LD








FCC ID : VPYLB1LD IC CN : 772C-LB1LD


A.2 Carrier Frequency Separation

Report No.: 17040026JMA-002


IC CN: 772C-LB1LD


Original: April 20, 2017 Revised: May 2, 2017 FCC ID: VPYLB1LD















FCC ID: VPYLB1LD IC CN: 772C-LB1LD








2480 MHz




FCC ID : VPYLB1LD IC CN : 772C-LB1LD


A.3 Number of Hopping Frequency







FCC ID: VPYLB1LD IC CN: 772C-LB1LD




FCC ID : VPYLB1LD IC CN : 772C-LB1LD


A.4 Time of Occupancy


Report No.: 17040026JMA-002


IC CN: 772C-LB1LD


Original: April 20, 2017 FCC ID: VPYLB1LD Revised: May 2, 2017














FCC ID: VPYLB1LD IC CN: 772C-LB1LD

