Test report No. : 11932168H-C-R1
Page : 137 of 139
Issued date : February 26, 2018
FCC ID : VPYLB1NX

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 11932168H-C-R1
Page : 138 of 139
Issued date : February 26, 2018
FCC ID : VPYLB1NX

Radiated Spurious Emission




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 11932168H-C-R1
Page : 139 of 139
Issued date : February 26, 2018
FCC ID : VPYLB1NX

Worst Case Position


Below 1GHz (Horizontal: X-axis/ Vertical: X-axis) 1 – 10 GHz (Horizontal: X-axis/ Vertical: X-axis) Above 10 GHz (Horizontal: Y-axis/ Vertical: Z-axis)

X-axis



Y-axis

0



End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124