Test report No. : 10003724H-A-R1
Page : 29 of 31
Issued date : March 12, 2013
Revised date : March 19, 2013
FCC ID : VPYLBWS

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1



Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 10003724H-A-R1
Page : 30 of 31
Issued date : March 12, 2013
Revised date : March 19, 2013
FCC ID : VPYLBWS

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 10003724H-A-R1
Page : 31 of 31
Issued date : March 12, 2013
Revised date : March 19, 2013
FCC ID : VPYLBWS

Worst Case Position (Horizontal: Y-axis/ Vertical: Z-axis)

X-axis



Y-axis



Z-axis



^{*} The test was performed on a jig board, on which the stripline design of 9.7 mm of the actual use distance between the module and antenna was made.

End of Report

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124