
Test report No.: 32IE0119-SH-01-A

Page : 87 of 89


APPENDIX 3: Photographs of test setup

Conducted emission









UL Japan, Inc. **Shonan EMC Lab.**


1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN


Telephone : +81 463 50 6400 Facsimile +81 463 50 6401


Test report No.: 32IE0119-SH-01-A

Page : 88 of 89

Radiated emission







UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401


Test report No.: 32IE0119-SH-01-A

Page : 89 of 89

Pre-check of the worst position







The axes are common in all antenna types.

UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401