Test report No. : 11774441H-B-R2
Page : 53 of 57
Issued date : October 4, 2017
FCC ID : VPYLB1MW

APPENDIX 3: Photographs of test setup

Conducted Emission



Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 11774441H-B-R2
Page : 54 of 57
Issued date : October 4, 2017
FCC ID : VPYLB1MW

Radiated Spurious Emission



Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Test report No. : 11774441H-B-R2
Page : 55 of 57
Issued date : October 4, 2017
FCC ID : VPYLB1MW

<u>Worst Case Position</u> <u>Antenna (Horizontal: Z-axis/ Vertical: Z-axis)</u>


X-axis



Y-axis



Z-axis




4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Test report No. : 11774441H-B-R2
Page : 56 of 57
Issued date : October 4, 2017
FCC ID : VPYLB1MW

<u>Worst Case Position</u> <u>Module (Horizontal: X-axis/ Vertical:X-axis)</u>

X-axis



Y-axis




Z-axis



4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 11774441H-B-R2
Page : 57 of 57
Issued date : October 4, 2017
FCC ID : VPYLB1MW

Worst Case Position



30 mm Antenna (Worst)



300 mm Antenna

End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN