Test report No.
 : 12862749H-A-R1

 Page
 : 46 of 48

 Issued date
 : July 22, 2019

 FCC ID
 : VPYLB1SU

#### **APPENDIX 3: Photographs of test setup**

## **Conducted Emission**




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 12862749H-A-R1 : 47 of 48 : July 22, 2019 : VPYLB1SU Page Issued date FCC ID

# **Radiated Spurious Emission**




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

 Test report No.
 : 12862749H-A-R1


 Page
 : 48 of 48

 Issued date
 : July 22, 2019

 FCC ID
 : VPYLB1SU

## **Worst Case Position**

### Below 1GHz (Horizontal: X-axis/ Vertical: X-axis) Above 1GHz (Horizontal: X-axis/ Vertical: Y-axis)



These antenna ports are for Sub GHz part.





**End of Report** 

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124