Test report No. : 12007719H-A-R2
Page : 31 of 32
Issued date : January 9, 2018
FCC ID : VPYLB1JS955

## **APPENDIX 3: Photographs of test setup**

# **Radiated Spurious Emission**




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 12007719H-A-R2
Page : 32 of 32
Issued date : January 9, 2018
FCC ID : VPYLB1JS955


## **Worst Case Position**


#### WLAN


Below 1GHz (Horizontal: X-axis/ Vertical: Y-axis) Above 1GHz (Horizontal: X-axis/ Vertical: Y-axis)

#### BT LE

Below 1GHz (Horizontal: X-axis/ Vertical:X-axis) Above 1GHz (Horizontal: X-axis/ Vertical:Y-axis)







#### **End of Report**

# UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124