Test report No. : 11050639H-A
Page : 64 of 67
Issued date : January 26, 2016
FCC ID : VPYLXRF026

#### **APPENDIX 3: Photographs of test setup**

## **Conducted emission**




Photo 1




Photo 2

## UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11050639H-A Page : 65 of 67 Issued date FCC ID : January 26, 2016 : VPYLXRF026

## **Radiated emission**



Photo 1




Photo 2

## UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124


Test report No. : 11050639H-A
Page : 66 of 67
Issued date : January 26, 2016
FCC ID : VPYLXRF026

#### **Worst Case Position**


Below 30 MHz Y-axis

Above 30 MHz Horizontal: X-axis / Vertical: Z-axis


#### X-axis



Y-axis



**Z**-axis




# UL Japan, Inc. Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11050639H-A
Page : 67 of 67
Issued date : January 26, 2016
FCC ID : VPYLXRF026

## With/Without Tag









**End of Report** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124