Test report No. : 10662332H-C-R1
Page : 117 of 119
Issued date : July 13, 2015
Revised date : July 28, 2015
FCC ID : VPYLB1CK

APPENDIX 3: Photographs of test setup

Conducted Emission



Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10662332H-C-R1
Page : 118 of 119
Issued date : July 13, 2015
Revised date : July 28, 2015
FCC ID : VPYLB1CK

Radiated Spurious Emission




Photo 1




Photo 2


UL Japan, Inc. Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10662332H-C-R1
Page : 119 of 119
Issued date : July 13, 2015
Revised date : July 28, 2015
FCC ID : VPYLB1CK

Worst Case Position
(Horizontal: X-axis/ Vertical: Y-axis)







End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124