Test report No. : 11932168H-A-R1
Page : 63 of 65
Issued date : February 26, 2018
FCC ID : VPYLB1NX

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 11932168H-A-R1 Page : 64 of 65

Issued date : February 26, 2018 FCC ID : VPYLB1NX

Radiated Spurious Emission




Photo 1



Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 11932168H-A-R1
Page : 65 of 65
Issued date : February 26, 2018
FCC ID : VPYLB1NX


Worst Case Position WLAN:

Below 1GHz (Horizontal: X-axis/ Vertical: X-axis) Above 1GHz (Horizontal: X-axis/ Vertical: Z-axis)


BTLE:

Below 1GHz (Horizontal: X-axis / Vertical: X-axis) Above 1GHz (Horizontal: Y-axis / Vertical: Y-axis)


X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124